


List of equipment needed

- Tape measure
- Adhesive Tape
- 1 mm/ 1.5mm Copper Filtration plate (10 x 10cm)
- 0.9/1.2 mm copper filtration Plate (30x30cm)
- Densitometer
- Ruler
- 'Set Square'.
- Telescopic luminance meter/optical sensor
- Metal ball of certain diameter
- Simple test tools, which are equally effective, can be made very quickly and easily e.g. a pin template.
- Densitometer



Enter any adverse findings in the room log book (**IER**).
Inform the radiographer in charge of Quality Assurance.
All results must be documented at least **once every three months**.

